CERTIFIED AGGREGATE TECHNICIAN TRAINING COURSE AGENDA

<u>Title – Time</u>	Subjects	Instructor	Reference
	Monday Morn Moderator: Ron V		
<u>Introduction</u>			
10:00	Opening Comments	Ron Walker	
to 10:15	Agenda/Manual Update		
CAPP Technician Prog	gram Responsibilities		
10:15 to 10:30	Industry Perspective	Bruce Mason	
Math for Aggregates			
10:30	Round-Off Rules	Ron Walker	Chp 1
to 11:15	Calculator Operation	(Mike Prather)	
	Mean		
	Standard Deviation		
	Moving Average		
Geology			
11:15 to 12:00	Origin	Nelson Shaffer (John Hill)	Chp 2
12:00 to 1:00	** LUNCH **		

Monday Afternoon

Moderator: Ron Walker

Aggregate Quality

1:00 to	Aggregate Types & Terms	Bob Rees (Eric Woodings/	Chp 2
2:00	Properties	Angela Rose)	Chp 3
	Quality Requirements		Chp 4

2:00 to 2:15 ** BREAK **

Tests for Quality Rating

2:15	Absorption	Bob Rees	Chp 4/Chp 10
to		(Eric Woodings/	
3:00	Abrasion Resistance	Angela Rose)	

Soundness

Deleterious Materials

Special Requirements

Deleterious Sample Kits

3:00 to 3:15 **BREAK**

Test for Quality Rating (continued)

3:15	Bob Rees
to	(Eric Woodings/
4:00	Angela Rose)

Help Session

7:30 Holiday Inn Express: Bob Lingerfelt/Trent Sanders
Steve Roseberry/Dave Hamilton
Jon Havens/Deana Miner
Trina Smart/Rich Brooks

Tuesday Morning Moderator: Ron Walker

Math	Homew	ork	Reviev	V

8:00 to 8:10	Answers & Discussion	Ron Walker (Mike Prather)	Handout
Processing			
8:10	Extraction	Bob Lingerfelt	Chp 5
to 9:00	Crushing	(Steve Roseberry/ George Williams)	
	Other Benefaction		
	Screening		
	Sand Production		
	Segregation		
	Stockpiling and Handling		
	Degradation		
	Contamination		
	Retrieval		
<u>Segregation</u>		Dave Hamilton	
9:00 to 9:30	Video	Mark Miller Kurt Sommer	
9:30 to 9:45	** BREAK **		
Test Equipment			
9:45	Suggestions	Stu Schwotzer	Chp 8
to 10:15	Manufacturers & Cost	(Jim Fletcher)	Handout
Test Equipment Verif	<u>ication</u>		
10:15 to 10:30	Procedures	Harley Phillips (Mike Prather)	Chp 8 ITM 211-9.0

<u>Lab Layout</u>

10:30	Suggestions	George Williams
to		(Bob Lingerfelt/
11:00		Steve Roseberry)

<u>Production Sampling</u>

11:00	Sampling Techniques	Steve Roseberry	Chp 9
to		(Bob Lingerfelt/	
11:30		George Williams)	

Stockpile Sampling

11:30	Safety	Dave Hamilton	Chp 9
to 12:00	Sampling Technique	Mark Miller Kurt Sommer	Chp 9/Video
12.00	Sampling Teeninque	Kurt Sommer	Chp 3/ Video
	Sample Reduction & Sample Size		Chp 9/Video

Tuesday Afternoon Moderator: Ron Walker

Aggregate Testing

	1:00	Decant		Dave Hamilton Mark Miller	Chp 10/Video
	to 2:30	Sieve Analysis		Kurt Sommer	Chp 10/Video
		Sieve Analysis (Dens	se Graded)		Chp 10/Video
		Fineness Modulus			Chp 10
		Moisture			Chp 10
		Coarse Aggregate Ar	ngularity		Chp 10
		Non-Durable Particle	es		Chp 10
		Flat and Elongated P	articles		Chp 10
		Frequency			Chp 11
		Homework Problems	S		Handouts
	2:30 to 2:45	** BREAK *	**		
Aggrega	ate Testing (cor	ntinued)			
	2:45 to 3:30			Dave Hamilton Mark Miller Kurt Sommer	Chp 10/Chp 11
<u>Diary</u>					
	3:30 to 3:45	CAPP Requirements Typical Day Example		Mike Prather (Ron Walker) Steve Roseberry (George Williams/ Bob Lingerfelt)	ITM 211 (10.0) Chp 11
CAPP C	Coordinated Tes	sting			
	3:45 to 4:00	Monthly Submittals		Mike Prather (Ron Walker)	ITM 211 (15.0)
Help Session					
	7:30	Holiday Inn Express:	Deana Miner/Ric	on Havens ch Brooks/ Mike Maggart Stu Schwotzer/Jeff Goshorn	

Wednesday Morning Moderator: Ron Walker

Aggregate Testing Homework Review

riggregate resting from	HOWOTK TCOTION		
8:00 to 8:15	Answers & Discussion	Ron Walker	Handout
Quality Control Plans			
8:15	CAPP QCP Requirements	Ron Walker	Chp 7
to 8:45	INDOT QCP Checklist QCP Addenda	(Mike Prather)	Chp 7
8:45	Quarry QCP	Jon Havens	Chp 7
to 9:45	Pit QCP	Rich Brooks (Mike Maggart)	Chp 7
9:45 to 10:00	** BREAK **		
Aggregate Production	Statistical Control		
10:00 to 10:15	CAPP Requirements	Ron Walker (Mike Prather)	ITM 211
10:15	Statistical Quality Control	Jim Plew Eric Reynolds	Chp 6
to 12:00	Understanding the Process & Steps for Managing Quality	Chuck Sanders	
	Statistical Concepts		
	Letter Counting Exercise		
12:00 to 1:00	** LUNCH **		

Wednesday Afternoon Moderator: Ron Walker

Aggregate Production Statistical Control (continued)

1:00 to 2:00	Z Value	Jim Plew Eric Reynolds Chuck Sanders	Chp 6
2:00 to 2:15	** BREAK **		
2:15	Control Chart Concepts	Tony Zander/Chuck Sanders	Chp 6
to 3:45	Control Chart Construction	(Ron Walker/Jim Plew/ Eric Reynolds)	ITM 211 (13.4)
	Control Chart Interpretation		
3:45 to 4:00	** BREAK **		
4:00 to 4:45	Percent Compliance	Jim Plew Eric Reynolds Chuck Sanders	Chp 6
4:45 to 5:00	Computer Demonstration	Jon Havens Trina Smart	
6:00	** DINNER **		
Help Session			
7:30	Trina Smart	nuck Sanders rs/Eric Reynolds/Bob Lingerfelt /Jon Havens/ George Williams zer/Rich Brooks/Steve Roseberry)	

Thursday Moderator: Ron Walker

Lab Demonstration at INDOT Materials & Tests
--

	8:00 to 12:00			Ron Walker, Mike Prather Bob Rees, Angela Rose Eric Woodings, Al Witty Jim Plew, Trinia Smart, Stu Sc	hwotzer	
	12:00 to 1:00	** LUNCH *	*			
Statistical Homework Review						
	1:00 to 1:30	Answers & Discussion	n	Tony Zander (Ron Walker)	Handout	
Audits						
	1:30 to 2:00	INDOT Audits		Mike Prather (Ron Walker)	Appendix D	
<u>Customer Expectations</u>						
	2:00 to 2:15	Producer Perspective		Ken Wanstrath		
	2:15 to 2:30	** BREAK				
	2:30 to 3:00	Contractor Perspective	e (PCCP)	Dick Newell		
	3:00 to 3:30	Contractor Perspective	e (HMA)	Dudley Bonte		
Review Session (Voluntary)						
	3:30 to 5:00			Ron Walker		
Help Session						
	6:30 Holiday Inn Express: Bob Lingerfelt/Jon Havens Trent Sanders/John Yzenas/Stu Schwotzer Trina Smart/George Williams/Rich Brooks Jim Plew					

Friday Morning Moderator: Ron Walker

Course Test

8:00 Written Exam to

12:00